
Meridian 1

M1250 and M2250 Attendant Consoles

Description

Document Number: 553-2201-117
Document Release: Standard 8.00
Date: October 1997

© 1989, 1997
All rights reserved

Printed in the United States of America

Information is subject to change without notice. Northern Telecom reserves the right to make changes in design or components as progress in engineering and manufacturing may warrant. This equipment has been tested and found to comply with the limits for a Class A digital device pursuant to Part 15 of the FCC rules.

SL-1 and Meridian 1 are trademarks of Northern Telecom.

Revision history

February 2, 1989

Standard for M1250 Console issued.

July 1989

Removed all references to MJ1250 console.

December 1989

Revised to incorporate corrections and updated information.

December 1990

This document is reissued to include updates and changes for X11 release 16. Updates are indicated by revision bars in the margins.

December 1991

Standard, release 4.00. This document is reissued to include technical content updates. Due to the extent of changes revision bars are omitted.

December 1994

Standard, release 5.00. This document is reissued to include updates and changes for X11 release 20 and M2250 Attendant Console enhancements. Updates are indicated by revision bars in the margins.

July 1995

Standard, release 6.00. This document is reissued to include updates and changes for X11 release 21. Updates are indicated by revision bars in the margins.

August 1996

Standard, release 7.00. This document updated for X11 release 22.

October 1997

Standard, release 8.00. This document is reissued to introduce Meridian 1 Attendant PC Software. Updates are indicated by revision bars in the margin.

Contents

Introduction	11
Related documentation	14
Description	15
Features	15
Physical details	15
Keyboard layout	15
Function keys	19
Switches	21
Shift key	21
Handset and headset jacks	21
LCD indicators	21
Display screen messages	22
Connections	22
Local console controls	23
Busy Lamp Field/Console Graphics Module	24
Installation	24
Power requirements	25
Display backlight power supply option	25
Attendant console operation	27
M1250/2250 configurations	27
QMT2 feature disabled	28
QMT2 feature enabled	28
Meridian 1 Attendant PC configuration	29

M1250/2250 feature key modes	30
M1250/2250 console diagnostics	30
M1250 failure codes	37
M2250 failure codes	39
Attendant console features	42
Time and date	42
Trunk Group Busy indicators	43
Incoming Call Indicators	44
Night service/busy	44
Enhanced Night Service	44
Attendant Blocking of DN	45
Attendant and Network Wide Remote Call Forward	45
Network Attendant Services	46
Call processing	46
ICI key assignments	46
Operating keys	47
Feature keys	48
Call Waiting indicator	49
Alarm indicators	49
Emergency Transfer	49
Attendant Administration	50
Collect Call Blocking	50
Alarm Management	51
Digital Trunk Interface—CIS	51
DPNSS Executive Intrusion	51
Attendant Monitor	52
Busy Verify and Barge-in Enhancement	52
Attendant Forward No Answer	53
Semi-Automatic Camp-On	53
Series Call	54
Powering and reset	54